# Creating Durable Concrete Floors

Bob Swan HD Concrete Floors



# Agenda:

- 1. Tipping Floor Deterioration.
- 2. Issues of safety and environmental compliance.
- 3. How long is your floor going to last? Let's measure it!
- 4. Repair: Full depth with Concrete? High Performance topping?
- 5. Contractor and material selection. Criteria?


Agenda:

1. Tipping Floor Deterioration.

#### **Market Trends For Transfer Stations**

## **Market Trends For Transfer Stations**

Increase in volume MSW



## **Market Trends For Transfer Stations**

Increased Equipment Size








## **Market Trends For Transfer Stations**

Increased Construction & Demolition



## **Market Trends For Transfer Stations**

Increased Chemical Attack: Leachate

Increased Chemical Attack Leachate

> Why is Leachate such a problem?



Increased
Chemical Attack
Leachate






Increased Chemical Attack Leachate





#### Increased Chemical Attack Leachate

A number sample were collected from landfills, transfer stations and anaerobic digesters.




Increased Chemical Attack Leachate

pH of normal

concrete: 10-12

Lowering pH = Acid Attack



#### Increased Chemical Attack Leachate



#### **Food Waste**



# **Normal Wear**





## **Chemical Attack**




#### **Normal Abrasion**



#### Increased Chemical Attack Leachate

Leachate ends up on tip floors a lot of different way.




Increased Chemical Attack Leachate



Increased Chemical Attack Leachate



Increased Chemical Attack Leachate



#### Increased Chemical Attack Leachate



#### Increased Chemical Attack Leachate



#### Increased Chemical Attack Leachate



Increased Chemical Attack Leachate

> Anaerobic Digester



Increased Chemical Attack Leachate


> Anaerobic Digester




#### Increased Chemical Attack Leachate



Increased Chemical Attack Leachate



#### Increased Chemical Attack Leachate



#### Increased Chemical Attack Leachate



# Agenda:

- 1. Tipping Floor (Concrete) Deterioration.
- 2. Issues of safety and environment.


When the worlds of SAFETY and FLOOR INTEGRITY collide







When the worlds of SAFETY and FLOOR INTEGRITY collide




















# Agenda:


- 1. Tipping Floor Deterioration.
- 2. Issues of safety and environment.
- 3. How long is your floor going to last? Let's measure it! For Safety. For Budget.


# Measuring the rate of concrete wear.

- 1. Monitor Tons/Day and Visual
- 2. Use of Wear Indicators
- 3. Laser Scanning

# Measuring the rate of concrete wear.

- 1. Monitor Tons/Day and Visual
- 2. Use of Wear Indicators
- 3. Laser Scanning





The Floor doesn't wear evenly









North Shore Marine Transfer Station NYC Sanitation Dept



North Shore Marine Transfer Station NY Sanitation Dept





# Measuring the rate of concrete wear.

- 1. Monitor Tons/Day and Visual
- 2. Use of Wear Indicators
- 3. Laser Scanning




























# Measuring the rate of concrete wear.

- 1. Monitor Tons/Day and Visual
- 2. Use of Wear Indicators
- 3. Laser Scanning

# Laser Scanning







Laser Scanning



# Laser Scanning





# Agenda:

- 1. Tipping Floor (Concrete) Deterioration.
- 2. Issues of safety and environment.
- 3. How long is your floor going to last? Let's measure it!
- 4. Repair: Full depth with Concrete? High Performance topping?



# **High Strength Concrete**

Cementitious
Fly Ash
Fine Aggregate
Coarse Aggregate
Water Content
Air Content (Entrapped)
HRWR
W/cm
Initial Slump (Water)
Final Slump
Shrinkage

6000 psi @ 28 days

680 lbs.

20%

1150 lbs.

1900 lbs.

(#467 Stone)

285 lbs.

1.5%

40 oz. +/- Type F

0.42

2" - 3"

6" - 8"

≤ 0.04% @ 28 days

**High Strength Concrete** 

What can be done to make the concrete better?






Fig. 3: Coarse aggregate used for the distribution center concrete (No. 467 stone [37.5 to 4.75 mm])

#### **QUALITY REQUIREMENTS OF AGGREGATE**

- Flaky and Elongated pieces sh
- Aggregate crushing value show than for wearing surfaces, and


- roads and pavements.
- Aggregate impact value shoul concrete other than for weari

surfaces, such as runways, roac


Abrasion value of aggregate who percent by weight for aggregate

# How Does Putting Fly Ash In Concrete Help?

# **Cement Particles**



# Fly Ash



**Greater Use Of Silica Fume** 

**Improves Strength** 

**Reduces Porosity** 



Silica Fume / Micro Silica
By product of Electric Arc
Furnaces used in making steel

Also rounded and 1,000 times smaller than cement particles.

### **Chemical Resistance**

Normal Strength: NC State recommended Concrete Mix for Tipping Floors
7,000 psi
.42 w/c ratio
Granite Aggregate



# Concrete:

# **Summary Recommendations:**

- 1. Abrasion resistance is directly related to aggregate hardness.
- 2. Lower W/C ratio improves abrasion resistance when concrete is exposed to leachate.
- 3.QC. Make sure you require cylinders taken at job site.



# Agenda:

- 1. Tipping Floor (Concrete) Deterioration.
- 2. Issues of safety and environment.
- 3. How long is your floor going to last? Let's measure it!
- 4. Repair: Full depth with Concrete?

# 5. High Performance topping?

High Performance Topping



# **Advantages of High-Performance Topping**

- 1. Far better performance over concrete
- 2. Reduced Down Time vs Concrete.

Installation over a weekend




Increased Chemical Attack Leachate





# **Increased Chemical Attack**



# **Chemical Resistance**







### **Chemical Resistance**

Normal Strength: NC State recommended Concrete Mix for Tipping Floors

7,000 psi .42 w/c ratio Granite Aggregate










### **Chemical Resistance**

Normal Strength: NC State recommended
Concrete Mix for Tipping Floors
7,000 psi
.42 w/c ratio
Granite Aggregate

### **High Performance Topping:**


15,000 psi.27 w/c ratioCalcined Bauxite Aggregate





Duration of exposure to organic acids (days)

## Surface life is 3-5x




Is Down Time an Issue?

Installation over a weekend



Is Down Time an Issue?



### **Bottom Line:**

- 1. If Concrete lasting 15 20 years and you can shut down for 10-14 days....concrete makes a lot of sense.
- 2. But if concrete is only lasting 5-10 years and/or you need to minimize shutdown, a high performance topping should be considered.

# **High Performance Topping**

Qualified Installer

### EucoFloor 404 Reference List 2019.pdf

#1 Project Name: Sunnyvale SMaRT Station

Owner: City of Sunnyvale

Description of Work: Transfer Station Floor Overlay

Square Feet Installed: 9,000 SF Installed Completion Date: February 23, 2018

Project Name: CLARTS

Owner: City of Los Angeles

Description of Work: Transfer Station Floor Overlay at Ports

Square Feet Installed: 7,200 SF & 7,000 SF Installed Completion Date: November 19,

2016 & January 27, 2018.

#3 Project Name: SBWMA Transfer Station & MRF Floor Repair

Owner: South Bayside Waste Management Authority
Description of Work: Repair Main Tipping Floor & MRF

Square Feet Installed: 7,800 SF & 4,970 SF Installed Completion Date: April 15, 2016 &

November 5, 2017

#4 Project Name: American Waste Transfer Station

Owner: Republic Services

**Description of Work:** Cast & Repour Port Edge / Overlay Main Transfer Station **Square Feet Installed:** 7,620 SF **Installed Completion Date:** November 11, 2017

**#5** Project Name: Grand Central Recycling & Transfer Station

Owner: Pete Perez

**Description of Work:** Transfer Station Floor Overlay

Square Feet Installed: 6,800 SF Installed Completion Date: June 6, 2015

#6 Project Name: Henderson Transfer Station

Owner: Republic Services

Description of Work: Overlay Main Tipping Floor / Cast & Repour Port Edge

Square Feet Installed: 3,600 SF 3,600 SF 3,000 SF Installed Completion Date: March

30, 2014 & April 12, 2015 & March 14, 2017

# **High Performance Topping**

Contractor should be certified/trained by manufacturer



The Euclid Chemical Company 19218 Redwood Road Cleveland, OH 44110 Phone: 800-321-7628 Fax: 216-531-9596 www.euclidchemical.com

August 19, 2014

Infrastructure Repair Services 163 Beaverbrook Road Lincoln Park, NJ 973-692-0002

> Certification for Infrastructure Repair Services (IRS) as Approved Contractor High Performance / High Durability Concrete Toppings

To Whom It May Concern:

The Euclid Chemical Company certifies that Infrastructure Repair Services (IRS) is approved, qualified and experienced regarding the use and installation procedures for products manufactured by The Euclid Chemical Company. The IRS crew has specifically been trained and is experienced in the use of Euclid Chemical products related to the repair and restoration of heavy duty flooring applications such as tipping floors in solid waste transfer stations. This includes surface preparation of the substrate concrete and application of the toppings.

Any questions, my contact information is listed below.

Sincerely,

# **High Performance Topping**

Warranty should guaranty bond of the topping to the substrate and no wear through during the warranty period.

### **Manufacturer Obligations**

The Euclid Chemical Company warrants its products to conform to the quality standards as stated in the specific product literature. The Euclid Chemical Company stands fully behind its products when used by qualified, competent persons following accepted construction procedures as outlined in our current published literature. In the event that a problem occurs, The Euclid Chemical Company reserves the right to have the true cause of the problem determined by accepted test methods performed by an independent, qualified concrete consultant or testing laboratory.

One Year Warranty Regarding Wear Resistance - The topping material EucoFloor 404 shall be guaranteed against premature wear and/or loss of bond to the substrate for one (1) years from the date if installation. If any portion of the topping wears through to concrete base before the warranty period expires, that portion shall be repaired or replaced by The Manufacturer and/or The Contractor. One year of wear will be defined as a calendar year from date of installation.

This warranty covers failure of repairs subject to normal and usual exposure, but excluding failures due to acts of God, unusual weather phenomena, failure of substrates, faulty or inadequate design, structural defects, building alterations, fire, abuse by unusual traffic and loading or other abnormal activities.

If upon laboratory/petrographic testing, it has been determined that the product was the cause of the repair failure, The Euclid Chemical Company will authorize the appropriate repairs to the

# **High Performance Topping**

Warranty should be written and cover Material and Labor

The Euclid Chemical Company



Material and Labor Sample Warranty

Warranty Number:

Project:

Owner:

Architect/Engineer:

Applicator: Products:

Square Footage:

Euclid Sales Representative: Date of Project Completion: Duration of Warranty: 1 year

# **High Performance Topping**

Warranty: Signed by all parties.

# Manufacturer By: Title: Date: Contractor By: Title: Date:

### Owner or Owner's Representative

By:

Title:

Date:

# **Key Items in Specification**

Qualified Contractor – Experienced with references of similar jobs

**Topping** – 6 successful projects within last 5 years

**Topping Warranty** – Material & Labor that covers Bond and Wear Through

**Concrete** – run job site QC regarding strengths

# The Good News

- You have choices regarding the quality of your tipping floor
- Those choices have significantly improved over the years




# **Bob Swan HD Concrete Floors**


Thank You




Is Down Time an Issue?



Increased Chemical Attack Leachate






# QUALITY REQUIREMENTS OF AGGREGATE

- Aggregates should be strong, hard, dense, durable, clear and free from veins and adherent coating.
- Aggregates should be free from injurious amounts of disintegrated pieces, alkalis, vegetable matter and other deleterious substances.
- Flaky and Elongated pieces should not be present in aggregate mass.
- Aggregate crushing value should not exceed 45 percent for aggregate used for concrete other than for wearing surfaces, and 30 percent for concrete for wearing surfaces, such as runways, roads and pavements.
- Aggregate impact value should not exceed 45 percent by weight for aggregates used for concrete other than for wearing surfaces and 30 percent by weight for concrete for wearing surfaces, such as runways, roads and pavements.
- Abrasion value of aggregate when tested using Los Angeles machine, should not exceed 30
  percent by weight for aggregates to be used in concrete for wearing surfaces and 50 percent
  by weight for aggregates to be used in other concrete.

### Concrete

Occupied Volume of Materials in One Cubic Yard of Concrete



Water/Cement Ratio (W/C)

Cement - 9%

**Water - 17%** 

Fine Aggregate - 33%

(Total Combined 60% to 75%)

**Coarse Aggregate - 41%** 

Air Content will vary (Typically) 1.5% to 8%

# **High Performance Topping**

- 1. Proven track record.
- 2. Installer should be VERY familiar with the product.
- 3. Performance should greatly exceed that of concrete.
- 4. Installation performed over a weekend for minimal downtime.
- 5. Warranty